



# Point Hope Airport

## 2001 Pavement Condition Index Values



# Point Hope Airport


Pavement Condition Index (PCI)  
Predicted Values for the Year 2002



## Point Hope Airport


# Point Hope Airport

Pavement Condition Index (PCI)  
Predicted Values for the Year 2003



# Point Hope Airport



Pavement Condition Index (PCI)  
Predicted Values for the Year 2004



## Point Hope Airport

# Point Hope Airport

Pavement Condition Index (PCI)  
Predicted Values for the Year 2005




## Point Hope Airport

PCI Value		General Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative/Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance/Overlay
<div></div>	55 - 59	Overlay/Reconstruction
<div></div>	40 - 54	Reconstruct
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct

Minimum PCI for Runway = 70  
Minimum PCI for Taxiway and Aprons = 60

[ ] Branch-Section Identifier  
Airport Code: PHO  
Site No.: 50601.\*A



# Point Hope Airport

Pavement Condition Index (PCI)  
Predicted Values for the Year 2006

